

ANGLES FOR TURNING TOOLS

These are the angles recommended in the book “Woodturning, a Foundation Course”

Roughing Out Gouges-----45 degrees

Spindle Gouges-----35 degrees

Chisels and Parting tools-----25 degrees

Bowl Gouges-----55 degrees

Scrapers-----80 degrees

These angles are a good place to start out with. They are not written in stone, and you may find other books with different information. I would try these and any others to see which ones work best for you.